

# Inspection of Sanitation Report of District Yamuna Nagar

1. Name of School

DAV Public Sr. Sec. School,  
Sadhaura ; Dist - Yamuna Nagar

2. Sanitation Condition

(a) Area of location

Sadhaura

(b) No. of rooms

32 Classrooms + 5 Labs

(c) Height of ceiling

11 Feet

(d) No. of air fans

130

(e) No. of exhaust fans

06

(f) Light emergency power supply

Generator is available

(g) Total no. of strength

758

3. Total no. of Urinals

15

Toilets

2 Toilets

4. Water Supply---Public Health/Ground Water

Ground water

(1 Boys + 1 Girls)

5. Chlorination

Yes

6. First Aid Box with Medicines

Yes

7. Protection of lighting

Yes

8. No. of Dustbins

40

9. No. of sweepers

03

Dated

11/03/24  
/2019

DISP-NO-460

Dated-20-04-24

Sanitation condition is Good in All Aspects.

Sadhaura

Principal  
D.A.V. Public Sr. Sec. School  
Sadhaura Distt. Yamuna Naga.

Sund  
HCMS-1  
Senior Medical Officer  
CHC Sadhaura (YNR)

Sund  
District Health Officer  
O/o Civil Surgeon  
Yamuna Nagar

From

Lab In charge  
DPHL- IDSP Laboratory  
Mukund Lal District Civil Hospital  
Yamuna Nagar

To

Senior Medical Officer,  
CHC Sadhaura.

No.

DML/YNR/2024/127

Dated: 15.4.2024

Subject: Bacteriological Examination of Water Samples

In reference to letter No 340

Dated: 10.04.2024

The report of water samples sent by you is as under: -

Sr. No.	Particulars of water Samples (With Complete Address)	OT Test Report For Chlorine	Test Report of Water for Bacteriological Examination
1.	DAV PUBLIC SCHOOL SADHAURA	NIL	No. of coliform organisms seen 0 Per 100ml. of water Water quality is Excellent (Class I) Water is fit for human consumption

*P. Bakshi*

Microbiologist  
Incharge DPHL- IDSP Laboratory  
Mukand Lal District Civil Hospital  
Yamuna Nagar